

USER MANUAL **ALUSYS**

Measuring system for heat flux and temperature survey



Warning statements



Putting a voltage of over 30 VDC to ALUSYS may result in permanent damage to the system.



ALUSYS has a rechargeable battery in its MCU. This battery needs periodic recharging and must be removed and stored separately if the equipment is stored for > 60 days.



ALUSYS has a rechargeable battery in its MCU. When replacing the battery, consult the manual of the internal battery holder and charge controller (model PS150).



ALUSYS has an internal battery in its electronics (model CR1000) in the MCU that powers the clock and the SRAM when external power is not supplied. This battery needs periodic replacement.



The high temperature cable of the HF01 heat flux sensor and its armour are electrical conductors. Use the silicone protection sleeve to avoid leakage of current.

Contents

| | |
|--|-----------|
| Warning statements | 2 |
| Contents | 3 |
| List of symbols | 4 |
| Introduction | 5 |
| 1 Ordering and checking at delivery | 9 |
| 1.1 Ordering ALUSYS | 9 |
| 1.2 Included items | 9 |
| 2 Instrument principle and theory | 10 |
| 2.1 MCU01 Measurement system | 10 |
| 2.2 Electronics in MCU01 | 10 |
| 2.3 Rechargeable battery and battery charge controller in MCU01 | 10 |
| 2.4 The Keyboard Display | 11 |
| 2.5 Heat flux sensor HF01 | 11 |
| 2.6 Adapter | 11 |
| 2.7 Optional ALUSYS with 3 x heat flux and temperature sensor | 11 |
| 3 Specifications of ALUSYS | 12 |
| 4 General directions for performing a heat flux and temperature measurement | 15 |
| 5 Arrival of a new ALUSYS | 16 |
| 5.1 Preparation before arrival | 16 |
| 5.2 Checking upon arrival | 16 |
| 6 System setup and functionality check | 17 |
| 6.1 Setup and functionality check in summary | 17 |
| 6.2 Software installation | 17 |
| 6.3 PC connection and defining the user interface | 18 |
| 6.4 Creating control buttons | 24 |
| 6.5 Functionality check | 24 |
| 7 Installation of sensors | 25 |
| 7.1 Site selection and installation | 25 |
| 8 Making measurements | 26 |
| 8.1 Controlling the measurement | 27 |
| 8.2 Measurement per sensor group - average | 28 |
| 8.3 Measurement for all sensors - allsens | 30 |
| 8.4 Realtime display of measurements | 31 |
| 8.5 Downloading data to the PC | 32 |
| 9 Maintenance and trouble shooting | 33 |
| 9.1 Employing new sensors / resetting sensor parameters | 33 |
| 9.2 Recommended maintenance and quality assurance | 34 |
| 9.3 Trouble shooting | 35 |
| 9.4 Calibration and checks in the field | 37 |
| 9.5 Storage of ALUSYS | 37 |
| 10 Appendices | 38 |
| 10.1 Variable names and description | 38 |
| 10.2 Battery removal | 38 |
| 10.3 EU declaration of conformity | 39 |

List of symbols

Quantities

| | Symbol | Unit |
|----------------|---------------|-----------------------|
| Heat flux | Φ | W/m ² |
| Voltage output | U | V |
| Sensitivity | S | V/(W/m ²) |
| Temperature | T | °C |
| Resistance | R | Ω |

Subscripts

| | |
|---|-------------|
| Property of thermopile sensor | sensor |
| Property of the surrounding environment | environment |

Introduction

ALUSYS is a measuring system for trend-monitoring and mobile survey of heat flux and surface temperature in industrial environments. Sensors and electronics have the robustness necessary for this application. Powered from a low-voltage rechargeable battery it is easy and safe to use. In its standard configuration the system consists of an MCU (Measurement Control Unit) in a metal housing and 12 x heat flux and surface temperature sensors of model HF01. Measured data are stored for later analysis.



Figure 0.1 the ALUSYS measuring system, for trend -monitoring and comparative surveys of heat flux and surface temperature in industrial environments. Connected to the MCU: one HF01 sensor, as well as the Keyboard Display.

ALUSYS measures heat fluxes and surface temperatures in demanding environments. It is designed for industrial surveys, for example surveys of aluminium smelters / furnaces.

The ALUSYS system employs dedicated sensors and electronics. Their high accuracy and sensitivity ensure that ALUSYS will still measure under circumstances where competing systems no longer perform reliable measurements; i.e. down to very low heat fluxes.

The measurement and control unit, MCU, has a robust aluminium housing and accepts 12 (order code ALUSYS12) or optionally 3 sensors (order code ALUSYS03).

The system generates a measurement file, including a time-stamp, heat flux and temperature for all sensors. The measurement is stored in the MCU and later downloaded to a PC. The user is responsible for data analysis.

A PC or the Keyboard Display may be used for real time measurement review and control of data storage and starting and stopping the measurement.

Powered and charged using a low voltage, ALUSYS is safe to use. The system can operate for a limited time on MCU's internal rechargeable battery.

For all information on the HF01 heat flux and surface temperature sensors, see the [HF01](#) manual. Optionally other sensor models may be used.

The standard system is equipped with one 15 m long extension cable with 2 connectors for every heat flux sensor.

ALUSYS advantages are:

- robust
- high accuracy, also measuring at low heat flux levels
- equipped with its own clock
- safe, low voltage 12 VDC power supply

Advantages of HF01 heat flux and surface temperature sensor relative to competing models are:

- robust, in particular at high temperatures
- fast response time, reduces the time needed for a survey

ALUSYS and the sensor model HF01 are most suitable for relative measurements, i.e. monitoring of trends relative to a certain reference point in time or comparing heat flux at one location to the heat flux at another location.

Also when performing relative measurements we recommend you to perform an on-site comparison to verify sensor performance. A comparison is made by mounting multiple sensors side by side, and comparing under conditions – temperature, mounting surface and local convection – representative of your test environment. One sensor must serve as a comparison reference. Typically this comparison reference sensor is not used for field measurements but stored in a safe place, so that the same comparison may be repeated at a later moment.

If the user wants to perform accurate absolute measurements, as opposed to relative measurements, we recommend that you calibrate sensors under "simulated service conditions". This is done by creating an environment that closely resembles the measurement conditions while generating a known heat flux; the calibration source might even be the object under test itself. Calibrations are typically traceable to electrical power (voltage and current) and length (surface area of the calibration source). We recommend to calibrate at different temperatures.

Under all conditions the user must make his own uncertainty evaluation and correction for systematic errors.

Options are:

- ALUSYS with 3 heat flux and temperature sensors (ALUSYS03)
- longer length low temperature extension cables with 2 connectors (specify cable length)
- use of other sensor models than HF01
- sensors with extended rated operating temperature range
- MCU with extended rated operating temperature range



Figure 0.2. HF01 heat flux and surface temperature sensor with frame with magnets




Figure 0.3 the ALUSYS measuring system;

(1) HF01 heat flux sensor (with magnet frame), (2) HF01 high temperature cable with silicone sleeve, (3) HF01 low temperature extension cable with connector at the cable end, (4) low temperature extension cables with 2 connectors, (5) PC or laptop (not part of the system). On or inside the MCU: (6) chassis connector for PC connection via USB, (7) chassis connector for power supply to internal battery charge controller, (8) rechargeable battery. Outside the MCU: (9) adapter (100 - 240 VAC), (10) Keyboard (LCD) Display. Items 6 to 9 are part of the MCU.




Figure 0.4 *The MCU in detail*

- (1) *chassis connector for communication with the PC / laptop via USB port*
- (2) *chassis connector for power supply to internal battery holder/ charge controller*
- (3) *red LED [ON] indicating the system receives power*
- (4) *power switch [ON/OFF]*
- (5) *switch for starting recording of measurements [TOGGLE]*
- (6) *green LED [ON] indicating the system is recording measurements.
When blinking consult Chapter 9.3*
- (7) *SUB-D connector for the Keyboard Display*
- (8) *chassis connectors for the individual heat flux and temperature sensors*

1 Ordering and checking at delivery

1.1 Ordering ALUSYS

The standard configuration of ALUSYS is equipped with 12 x HF01 heat flux and temperature sensor, each with 0.9 m high temperature cable and 3.5 m low temperature extension cable and connector at the cable end. Each heat flux sensor is supplied with 15 m low temperature extension cable with 2 connectors.

Common options are:

- ALUSYS system with 3 x HF01
- low temperature extension cables with 2 connectors (specify cable length)
- other sensor models than HF01
- sensors with extended rated operating temperature range
- MCU with extended temperature range

1.2 Included items

Arriving at the customer, the delivery should include:

- carrying case
- ALUSYS
 - 12 or 3 x HF01 with connector at cable end
 - 1 x MCU01
- adapter 18 VAC
- USB cable
- RS-232 cable (9-pin)
- ALUSYS software (on USB flash drive)
- Loggernet software (on CD-ROM)
- SC USB driver software (on CD-ROM)
- 1 x product certificate ALUSYS
- 12 or 3 x product certificate HF01
- 12 or 3 x HF01 low temperature extension cable with 2 connectors 15 m
- Keyboard Display with cable

2 Instrument principle and theory

2.1 MCU01 Measurement system

MCU01 is a high-accuracy battery-powered measuring system inside a robust housing. It is equipped with a clock and memory. It measures the voltage output of heat flux sensors as well as thermocouples. It has an on-board temperature sensor that acts as a cold junction measurement for the thermocouples. The cold junction temperature can be read from the Ptemp variable (ALUSYS03) or from AM25Ttemp variable (ALUSYS12).

MCU is equipped with on [ON-OFF] button to activate power and a [MEASUREMENT] button to manually start and stop a measurement and data storage of all sensors. MCU communicates with a PC through its Loggernet user interface software. It can also be connected to the Keyboard Display.

The MCU is running the ALUSYS software. The software allows 3 measurements:

- [average] measurement: average heat flux and temperature for a group of 3 sensors. The data are stored for every individual sensor over a single preset time interval. In case you employ 12 sensors there are 4 x groups. This measurement allows you to move around sensors per group on a large installation.
- [all sensors] measurement: average heat flux and temperature for all sensors. Data are stored for all individual sensors at a preset time interval until stopped. This measurement is used for long-term monitoring using all sensors
- [sensor details]: stored on command. To store sensor parameters and internal battery voltages.

MCU's rated temperature range is limited by the formal battery charging and discharging specifications. In practice MCU will continue working at lower temperatures, but at an unspecified battery capacity.

2.2 Electronics in MCU01

The electronics in MCU01 is a model CR1000 measurement and control system. The USB connection on the MCU connects the CR1000 to a PC. As an alternative the RS232 connector is used to connect the CR1000 to the Keyboard display.

2.3 Rechargeable battery and battery charge controller in MCU01

The MCU contains a model PS150 charge controller / battery holder. The rechargeable battery is a 7Ah Lead Acid battery as used in small motorcycles. The charge controller accepts 18 to 24 VAC RMS or 16 to 40 VDC, and supplies an unregulated 12 VDC output, which is used to power the MCU electronics.

In case the battery output drops below 10 VDC, MCU's green LED will slowly blink [ON-OFF-ON-OFF] as a warning (see chapter 9.3).

This battery needs periodic recharging. We recommend recharging the battery every month. It must be removed and stored separately if the equipment is stored for > 60 days. Consult the battery manufacturer for statements on battery lifetime.

MCU's rated temperature range is limited by the formal battery charging and discharging specifications. In practice MCU will continue working at lower temperatures, but at an unspecified battery capacity.

2.4 The Keyboard Display

The Keyboard Display is a simple user interface with a LED screen and a small number of keys. Using the display you can view realtime data, control the experiment: start and stop measurements and data storage.

The Keyboard Display offers a simple alternative to using a PC as user interface.

Keyboard Display and PC cannot be used simultaneously.

2.5 Heat flux sensor HF01

For the measurement principle and theory of the HF01 heat flux sensor, see the HF01 manual.

Heat flux sensors have individual sensor properties, such as their sensitivity and possibly their temperature dependence. It is important that the MCU has the right sensor information entered into its internal software for each input channel.

Optionally other sensor models may be supplied instead of HF01.

2.6 Adapter

The adapter supplied with ALUSYS is an 100/240 VAC Desktop AC-DC Adapter 24 VDC @ 1.67 A. The external plug on the MCU is connects the adapter to the internal battery charge controller.

2.7 Optional ALUSYS with 3 x heat flux and temperature sensor

This manual is written for the standard version with 12 x heat flux and temperature sensor.

The optional version with 3 sensors:

- is supplied with 3 x sensor
- is supplied with 3 x chassis connector on the MCU
- does not have an internal multiplexer; cannot accept more channels without significant modification
- uses the [average] measurement per 1 x sensor, and not for a group of 3 x sensor

3 Specifications of ALUSYS

ALUSYS is a system for on-site measurement of heat flux and surface temperature in demanding environments. The system is equipped with MCU high-accuracy electronics in a robust housing, and several (12 x, optionally 3 x) heat flux and temperature sensors of model HF01. Optionally other sensor models may be used. The sensors are mounted on the surface under test. The system includes Loggernet user interface software for use on a PC, an adapter for power supply and a Keyboard Display for realtime readout and control of the measurement in the field. Working on 12 VDC it is safe. The system works independent of mains power on its own battery for > 24 hours. A PC is not included. Data review and analysis is the responsibility of the user.

Table 3.1 *Specifications of ALUSYS (continued on next page)*

| ALUSYS SPECIFICATIONS | |
|---|---|
| Description | Measuring system for heat flux and temperature survey |
| Number of measurement locations | 12 (see options) |
| Measurand | heat flux (12 x) |
| Measurand in SI units | heat flux density in W/m ² |
| Measurand | surface temperature (12 x) |
| Measurand in SI units | temperature in °C |
| Time registration | on board clock, synchronised via user interface on PC |
| Required data analysis | to be performed by the user |
| Heat flux sensors (see options) | model HF01 , high temperature heat flux sensor, with frame with magnets, with connector at cable end |
| Extension cables | for every heat flux sensor: 1 x low temperature extension cables with 2 connectors (length 15 m) |
| Rated operating temperature ranges | HF01 with high temperature cable: -30 to 550 °C low temperature extension cable: -30 to 240 °C MCU: -15 to +50 °C MCU: non-charging -20 to +50 °C Keyboard Display: -25 to +50 °C |
| IP protection class | HF01 & high temperature cable: IP68 low temperature extension cable: IP67 MCU and Keyboard Display: IP63 adapter: IP60 |
| Rated operating relative humidity range | 0 to 100 % (non-condensing) |
| Gross weight | approx. 17 kg (no sensors, no extension cables) |
| Net weight total ALUSYS excluding carrying case | 15 kg (no sensors, no extension cables) |

Table 3.1 Specifications of ALUSYS (started on previous page, continued on next page)

| MCU01 | |
|--|--|
| Measurand | analogue voltage and conversion to heat flux using the sensitivities of the heat flux sensors |
| Voltage measurement accuracy | 0.5×10^{-6} V |
| Measurand | analogue voltage and conversion to temperature using the panel temperature and general thermocouple type K characteristics |
| Measurand | panel temperature to serve as a cold junction reference temperature for the thermocouple measurements |
| Measurand | date and time, rechargeable battery voltage, internal system battery voltage |
| Data display | on Keyboard Display |
| Sample rate | 1 1/s |
| Stored measurement definition | [average] measurement: average heat flux and temperature for a group of 3 sensors, stored for every individual sensor over a single preset time interval [all sensor] measurement: average heat flux and temperature for all sensors stored for all individual sensors at a preset time interval until stopped [sensor details]: stored on command |
| Storage capacity | > 30 days |
| Rated power supply and charging voltage range | 16 to 40 VDC |
| Connection to PC | via USB |
| USB cable length | 1.9 m |
| User interface on PC | Loggernet software (supplied on CD-ROM) |
| Memory capacity | 4 MB > day of data |
| System requirements for use with PC | Windows XP and later, CD-ROM drive, USB port, and USB or RS-232 (COM) port |
| Program running on MCU | ALUSYS program (supplied on USB flash drive) |
| Power switch / LED | red LED [ON] when power is supplied to MCU |
| Measurement switch / LED | TOGGLE, green LED [ON] when measurement active and data is stored |
| MCU dimensions | $(320 \times 320 \times 120) \times 10^{-3}$ m, brackets of 42×10^{-3} m |
| Connection to Keyboard Display | via SUB-D connector |
| ADAPTER | |
| Adapter rated power supply | 100 - 240 VAC, 50 / 60 Hz |
| Adapter output | 18 VAC @ 1.2 A |
| BATTERIES | |
| Rechargeable battery | 12V 7Ah Sealed Lead Acid Battery, for example EnerSys Genesis NP7-12 |
| Battery low indicator | green LED |
| Rechargeable battery disposal | follow local regulations |
| Measurement time interval on a fully charged battery | > 24 hr |
| Required charging time interval | 12 hr |
| Internal system battery | powering the clock and the SRAM when no external power is connected. Type: 3.6 VDC, 1.2 Ahr, 1/2 AA size cell. |
| HF01 HEAT FLUX SENSOR | |
| Specifications | see HF01 manual |

Table 3.1 *Specifications of ALUSYS (started on previous pages)*

| INSTALLATION AND USE | |
|---|--|
| Performing a representative measurement | see the chapter on recommended practices for use and the sensor manual |
| Installation | see the chapter on recommended practices for use and the sensor manual |
| Cable extension | use optional low temperature extension cable with 2 connectors |
| CALIBRATION AND FUNCTIONAL TEST | |
| Production report | included |
| Performance verification | via functional test |
| Calibration traceability | HF01 and MCU are traceable to SI units |
| Uncertainty of calibration of heat flux sensors | $\pm 20\%$ ($k = 2$, for model HF01) |
| Recommended recalibration interval | 2 yr |
| On-site performance verification | see the chapter on calibration and checks in the field: for accurate trend monitoring and relative measurements: perform an on-site comparison. if you want to perform accurate absolute measurements, as opposed to relative measurements we recommend that you calibrate sensors under "simulated service conditions". |
| MEASUREMENT ACCURACY | |
| Uncertainty of the measurement | statements about the overall measurement uncertainty can only be made on an individual basis. also see the HF01 manual. |
| VERSIONS / OPTIONS | |
| Extension cable | low temperature extension cable with 2 connectors (standard length 15 m, specify length in m) |
| Other sensors | other sensor models than HF01 |
| Less sensors | ALUSYS with 3 x heat flux and temperature sensor |
| Higher temperature range sensors | sensors with extended rated operating temperature range |
| Higher temperature range MCU | MCU with extended rated operating temperature range |

4 General directions for performing a heat flux and temperature measurement

There are no standard operating practices for using ALUSYS. We recommend reading the manual of the sensors connected to ALUSYS. Typically this is sensor model HF01.

5 Arrival of a new ALUSYS

5.1 Preparation before arrival

As a preparation, preferably the operator should read this manual.

Table 5.1.1 *List of items that the operator should have available*

| ITEM | REMARKS |
|-------------|--|
| PC | running Windows XP or later, with CD-ROM drive and one free USB port |
| Power | 110-240 VAC |

5.2 Checking upon arrival

When the instrument arrives, it is recommended to check if the delivery is complete. The list of delivered items can be found in the chapter on Ordering and checking at delivery. For the most common overall system check, see the next chapter.

6 System setup and functionality check

The user should be familiar with the warning statements given on page 2 of this manual.

6.1 Setup and functionality check in summary

Table 6.1.1 summarises the setup procedure and a quick system test. The remainder of this chapter explains this in detail.

Table 6.1.1 *Summary of procedures for system setup and a quick system test*

| PROCEDURE | |
|------------------|--|
| 1 | install the USB driver |
| 2 | install the Loggernet user interface software |
| 3 | connect the MCU to power using the Adapter |
| 4 | connect the MCU to the PC, using the USB cable, switch on the MCU power |
| 5 | connect at least 2 sensors: test the response of the sensors by touching them with your hand |
| 6 | make contact with the MCU through Loggernet get the heat flux and temperature data on screen |
| 7 | verify that the right serial numbers, sensitivities, reference temperatures and temperature coefficients are entered in the ALUSYS program |
| 8 | choose which measurement to perform (average, or all-sensors) |
| 9 | check the functionality of the Keyboard Display |
| 10 | try downloading data to a PC |

6.2 Software installation

Table 6.2.1 *Procedures to install software on the PC*

| PROCEDURE | |
|------------------|--|
| 1 | make a backup of all received files, store the serial number and user access code of the Loggernet software in a safe place |
| 2 | install the USB driver (delivered on CD-ROM) |
| 3 | install the LoggerNet software starting the windows explorer and double clicking the application "Autorun". The latest versions of LoggerNet are delivered on CD-ROM. The installation procedure is straightforward. The directory in which the software is installed is usually called LoggerNet. |
| 4 | the ALUSYS software is delivered on a USB flash drive. File extensions are: .CR1 & .DLD. upon delivery the ALUSYS software is already installed on the MCU and "running on power-up". |

6.3 PC connection and defining the user interface

Table 6.3.1 summarizes the procedure of connecting to the MCU and creating a user interface. Step 3 and 4 are explained in detail in this section.

6.3.1 Loggernet user interface




Figure 6.3.1.1 The main menu of Loggernet. The MCU can be connected through [Setup]. During normal operation only [Connect] is used

Table 6.3.1.1 Guidelines on how to make contact with the MCU through Loggernet

| PROCEDURE | |
|------------------|--|
| 1 | select [SETUP] - [Add] |
| 2 | select CR1000, and give it the appropriate name: 'ALUSYS' |
| 3 | select [Direct Connect] |
| 4 | select what COM port (typically COM port 1) you plugged the cable in. Set delay at 0. |
| 5 | set Baud Rate to 115200 |
| 6 | set Dataloggers' clock if the datalogger time does not match the server time |
| 7 | check if ALUSYS v1705.cr1 is running. If the program is not running, browse to where the ALUSYS program is situated (supplied with the system on a USB flash drive) and click [OK] |
| 8 | select AllSens in Tables. Make sure option Table Collected during Data Collection is turned [ON]. Data file option should be: Append to File. Output file should be: C:\CampbellSci\LoggerNet\CR1000_AllSens.dat |
| 9 | Repeat preceding operation for tables: AvgSens1 AvgSens2 AvgSens3 AvgSens4 SensDet |
| 10 | we recommend to select 'Scheduled Collection Enabled' |

6.3.2 Get real time heat flux and temperature data

From the main menu open the [Connect] screen.




Figure 6.3.2.1 The screen in Connect. During normal operation the [Numeric] and [Graphs] buttons are used for on-screen data display

Before starting operation a few elementary steps should be performed:

Table 6.3.2.1 *Verification of contact, synchronising data and time*

| | | |
|---|--|---|
| 1 | Press [connect] in the lower left hand corner | The lower left hand corner of the screen shows "connected", and the clock synchronisation of the upper right hand corner shows that the Datalogger time/date is running |
| 2 | Press Set Station Clock to set it to the correct date and time | |

Check that the correct program is running:

Table 6.3.2.2 *Verification of program*

| | | |
|---|---|---|
| 1 | Press [File Control] in the middle of the toolbar on top | The 'File Control' panel should open |
| 2 | Check that alusys v1705.CR1 is present on the system | |
| 3 | Check that ALUSYSLIBv1701.dld is present on the system | |
| 4 | If either of the files are missing, press [send] on the upper left of the tool bar | An upload dialogue box should appear |
| 5 | Browse to where the Alusys program is situated and upload both files, regardless of them being present already. Do not choose any run options when uploading the files! | The program will alert when uploading has finished |
| 6 | After uploading both files, select the alusys v1705.CR1 and press [Run Options] in the middle of the toolbar on top | The run dialogue box should appear |
| 7 | Select run now and run on power-up options. Clearing previous data is optional. Press Ok | The alusys v1705.CR1 program should start recompiling and will alert when it starts running |




Figure 6.3.2.2 The 'File control' panel

On the [Connect] screen, the [numeric display] can be used to view various parameters numerically. Parameters can be added through the [Add] menu.

Definitions of the parameters used in the program are given in Appendix 10.1.




Figure 6.3.2.3 A [Numeric Display] is used to view the value of parameters numerically. Parameters can be added by pressing [Add], selecting [Public] and dragging the parameters to be viewed to the table. We recommend to display sensor serial number, heat flux and temperature for each sensor

The [graph display] can be used to view various parameters graphically. Parameters can be added through the [add] menu.




Figure 6.3.2.4 The Graph Display can be used to view the value of parameters graphically. Parameters can be added by pressing [+], selecting [Public] and dragging the parameters to be viewed to the table. By right clicking on the parameter, color and axis can be changed

6.4 Creating control buttons

Activating a flag triggers pre-programmed functions for the MCU. Ports are indicators for the status of a control port. We use ports and flags as buttons to control the measurement.

Create the following screen in the [CONNECT] screen choosing [PORTS AND FLAGS] and [ADD], pasting from [PUBLIC]

Pressing the green button left of the name of the flag, activates this flag.




Figure 6.4.1 The [Ports and Flags] display

6.5 Functionality check

Table 6.5.1 Testing the functionality of the system

| PROCEDURE | |
|---|---|
| Connect sensors | |
| Collect calibration certificates | Heat flux sensors are individually calibrated and have individual properties. Sensor parameters can be found on their calibration certificates. |
| Check whether the correct serial numbers, sensitivities, reference temperatures and temperature dependencies are entered in the ALUSYS program running on the MCU | Use the [NUMERIC] screen and check the values of [Esen], [Tref], [TD], and [SN] for each sensor. The values can be changed by double clicking on it and entering the new/correct value. |
| Push the flag [ALLSTART] to start measuring and storing data. | Verify that the green LED is [ON] |
| Test the heat flux and temperature response of individual sensors | Touch sensor with your hand or expose to a stronger heat source. |

7 Installation of sensors

7.1 Site selection and installation

Table 7.1.1 *Recommendations for installation of heat flux sensors and temperature sensors*

| | |
|-----------------|---|
| General | Consult the HF01 manual Take into account local safety regulations |
| Sensor mounting | Avoid any air gaps between sensors and wall. Brush off any corrosion with a steel brush |

8 Making measurements

Having prepared the system according to the directions given in chapter 6 & 7, the system is now ready for measuring. See the next paragraph for explanation of the experiment control.

A typical measurement sequence is as follows:

Table 8.1 *Typical measurement sequence*

| | | |
|----|---|--------------------|
| 1 | switch the system [ON], | red LED [ON] |
| 2 | connect PC or Keyboard Display | |
| 3 | connect sensors to the system | |
| 4 | push flag [Sensdet] | stores sensor data |
| 5 | install sensors on measurement location | |
| 6 | choose between the [average] measurement, per group of 3 sensors, or the [all sensor] measurement if needed change [interval] via the numeric screen (typing the value and confirming with [ENTER], or via the Keyboard Display) | |
| 7 | for the [average] measurement press flags [sens 1] to [sens 4] for the [all sensor] measurement press flag [allstart] | green LED [ON] |
| 8 | measure | |
| 9 | the [average] measurement will stop measuring automatically at [interval] setting the [all sensor] measurement can be stopped by pressing flag [allstop] | green LED [OFF] |
| 10 | regularly check the measurements by verification of data files and by viewing actual data in the graphs / on the keyboard display | |

8.1 Controlling the measurement

Pressing the green button left of the name of the flag, activates this particular flag.




Figure 8.1.1 The [Ports and Flags] display in the [numeric] screen

Table 8.1.1 Explanation of the different flags and ports

| | |
|---------------|---|
| Port Status 1 | multiplexer activity |
| Port Status 2 | multiplexer activity |
| Port Status 3 | measurement active |
| Port Status 4 | - |
| Port Status 5 | - |
| Port Status 6 | - |
| Port Status 7 | - |
| Port Status 8 | - |
| Sens 1 | measure sensor group 1 (optionally measure sensor 1) |
| Sens 2 | measure sensor group 2 (optionally measure sensor 2) |
| Sens 3 | measure sensor group 3 (optionally measure sensor 3) |
| Sens 4 | measure sensor group 4 (Note: this flag is not used in ALUSYS03 with only 3 sensors) |
| Allstart | all sensors [ON]: continuous measurement |
| Allstop | all sensors [OFF]: stop continuous measurement |
| Status | [ON] if any measurement is running |
| Reset | interrupt all ongoing measurements |
| Sensdet | write sensor details to memory |
| DebugMode | sets the MCU in debug mode; every 30s the system will log debug data |
| ResetSettings | resets the system back to factory default settings and resets all active measurements |

8.2 Measurement per sensor group - average

With the average instruction the user measures heat flux and temperature of a group of 3 sensors during a set time interval, and store the average. The [interval] default value is 30 s. The output is an average of measured data over that interval. After the interval, the measurement stops automatically.

8.2.1 Control via PC

Table 8.2.1.1 *Setting the [interval] value, via USB to PC*

| | |
|---|-----------------|
| open the [connect] screen | |
| select [Interval] from the [public] table | default is 30 s |
| change the value and press [ENTER] | |

To start the averaging measurement:

Table 8.2.1.2 *Performing a measurement of a group of sensors for a short time interval, via USB to the user interface on PC*

| | |
|--|-----------------|
| open the [connect] screen | |
| select [ports and flags] | default is 30 s |
| press [sens 1] to activate sensors 1, 2 and 3 | |
| press [sens 2] to activate sensors 4, 5 and 6 | |
| press [sens 3] to activate sensors 7, 8 and 9 | |
| press [sens 4] to activate sensors 10, 11 and 12 | |

8.2.2 Control via Keyboard display

The user may also use the keyboard display to control the measurement:

Table 8.2.2.1 *Performing a measurement of a group of sensors for a short time interval, via the Keyboard Display*

| | |
|--|---|
| after startup, press any key on the Keyboard Display | [Heat Flux Meas] will appear on screen |
| select [measurement par] with the cursor confirm with [ENTER] | [Measurement par] will appear on screen |
| the parameters can be changed [Esc] to go back to the [Start] screen | [ENTER] and use numeric keys |
| [Start] Screen, press [Measurement Ctrls] | [Measurement ctrls] appears on screen |
| select the required [Avg group], [ENTER] | changes to [TRUE]. Measurement [ON], green LED [ON] |
| [Dev status] will change to [TRUE] | |
| measurement stops automatically | green LED [OFF] |



Figure 8.2.2.1 activating the measurement via the Keyboard Display

8.3 Measurement for all sensors - allsens

With the 'allsens' instruction you measure heat flux and temperature of all connected sensors until manually stopped. The data is stored at a time interval [scanrate].

8.3.1 Control via PC

Table 8.3.1.1 *Setting the [scanrate] value, via USB to PC*

| | |
|---|------------------|
| open the [connect] screen | |
| select [scanrate] from the [public] table | default is 1 min |
| change the value and press [ENTER] | |

For the actual measurement:

Table 8.3.1.2 *Performing an all sensor measurement, via USB to PC*

| | |
|--|------------------|
| open the [connect] screen | |
| select [ports and flags] | default is 1 min |
| press [allstart] to activate all sensors | green LED [ON] |
| press [allstop] to stop all sensors | green LED [OFF] |

8.3.2 Control via Keyboard Display

You may also use the Keyboard Display to control the measurement:

Table 8.3.2.1 *Performing an all sensor measurement, activated by the Keyboard Display*

| | |
|--|---|
| after startup, press any key on the Keyboard Display | [Heat Flux Meas] will appear on screen |
| select [measurement par] with the cursor confirm with [ENTER] | [Measurement par] will appear on screen |
| the parameters can be changed [Esc] to go back to the [Start] screen | [ENTER] and use numeric keys |
| [Start] Screen, press [Measurement Ctrls] | [Measurement ctrls] appears on screen |
| select [start measure], [ENTER] | changes to [TRUE]. Measurement [ON], green LED [ON] |
| [Dev status] will change to [TRUE] | |
| [STOP MEASURE], [ENTER] Measurement stops | green LED [OFF] |

8.4 Realtime display of measurements

Display of realtime data is possible via PC or Keyboard Display:

Table 8.4.1 Viewing realtime measurements on the PC

| | |
|-------------------------------------|------------------------|
| open the [connect] screen | |
| select [graph] or [numeric display] | |
| Select [public] | select required fields |
| press [allstop] to stop all sensors | green LED [OFF] |

Table 8.4.2 Viewing the realtime measurements on the Keyboard Display

| | |
|--|--|
| after startup, press any key on the Keyboard Display | [Heat Flux Meas] will appear on screen |
| Select [current sens val] with the cursor | measurement values will appear on screen |
| confirm with [ENTER] | |




Figure 8.4.1 Screenshot of the Keyboard Display, showing values of heat flux and temperature for sensors 1 to 4

8.5 Downloading data to the PC

The measurement data are stored in the CR1000 electronics of the MCU. These data can be retrieved for further analysis.

Table 8.5.1 Retrieval of measurement data from the MCU to the PC

| PROCEDURE | |
|-----------|---|
| 1 | detailed measurement data can be retrieved using [Collect Now] in the [Connect] screen |
| 2 | when retrieving data, immediately make a backup. For example by saving the data on memory card or hard disk |
| 3 | details regarding data analysis can be found in the manual of the sensors |
| 4 | default directory: C:\CampbellSci\LoggerNet\ |

Table 8.5.2 Data are stored in 3 separate files

| INFORMATION | FILENAMES | STORED DATA PER SENSOR |
|----------------------------------|--|---|
| 1 Sensor and battery | CR1000_SensDet.dat | SN Esen TD Tref minimum voltage rechargeable battery minimum voltage lithium battery |
| 2 Interval data per sensor group | CR1000_AvgSens1.dat CR1000_AvgSens2.dat CR1000_AvgSens3.dat CR1000_AvgSens4.dat | Avgflux AvgTs E (effective sensitivity at that temperature) Interval |
| 3 All sensor data | CR1000_AllSens.dat | E Flux Ts Scanrate |

The files are comma separated ASCII. They can easily be imported in Excel if the user uses the following procedure:

Table 8.5.3 Procedure for getting the ASCII-data in an Excel file

| PROCEDURE | |
|-----------|--|
| 1 | open Excel |
| 2 | choose [Open file] and select the desired data file |
| 3 | choose [Separated] in Step 1 and select Next |
| 4 | select [Comma] at [Separation Signs] and uncheck [Tabs] then select [Next] |
| 5 | if you have the [comma] assigned as the [decimal separator], select [Advanced] |
| 6 | if you have the [comma] assigned as the [decimal separator], choose [.] (dot) as [decimal] and [,] (comma) as [thousands] separator. Select [OK] |
| 7 | select [Finish] |

9 Maintenance and trouble shooting

9.1 Employing new sensors / resetting sensor parameters

Heat flux sensors are individually calibrated and have individual sensitivities. A certain sensor model also has a calibration reference temperature and temperature dependence. The serial number of the sensor can typically be found between the metal cable and PTFE cable. Its sensitivity, reference temperature and temperature dependence can be found on its calibration certificate.

Table 9.1.1 *Display and change sensor properties*

| | |
|---|--|
| use the [Numeric Display] from the [Connect] screen | |
| sensitivity = Esen | |
| temperature dependence = TD | |
| calibration reference temperature = Tref | |
| double-click the numeric value of Esen for Sensor 1 and change it to the value on its certificate | this sensitivity is stored in the file CR1000_USB_SensDet.dat |
| note that the sensitivity values should be entered in $\times 10^{-9}$ V/(W/m ²) | for sensor model HF01, enter only the first three digits from the calibration certificate, usually a number around 600 |
| the calibration reference temperature Tref | for model HF01 this is 90 °C |
| the temperature dependence TD | for model HF01 this is 0.0015 / K |
| repeat this operation for the value of Esen, Tref and TD of all other sensors | press [Sensdet]: all the values of sensitivity are stored in the file CR1000_USB_SensDet.dat |
| open [ports and flags] press [Sensdet]: all the values of sensitivity are stored in the file CR1000_USB_SensDet.dat | |

9.2 Recommended maintenance and quality assurance

ALUSYS measures reliably at a low level of maintenance. Unreliable measurement results are detected by scientific judgement, for example by looking for unreasonably large or small measured values. The preferred way to obtain a reliable measurement is a regular critical review of the measured data, preferably checking against other measurements, or by comparing results of the two heat flux sensors and two thermocouples when mounted side by side.

Table 9.2.1 *Recommended maintenance of ALUSYS. If possible the data analysis is done on a daily basis*

| MINIMUM RECOMMENDED ALUSYS SENSOR MAINTENANCE | | | |
|--|----------------------------|--------------------------|---|
| | INTERVAL | SUBJECT | ACTION |
| 1 | every measurement campaign | review sensor parameters | verify that the sensor serial numbers and parameters are correctly set. |
| 2 | every measurement campaign | on-site comparison | perform an on-site comparison of sensors, see appendix on on-site testing |
| 3 | every measurement campaign | storage | if the MCU is stored for more than 60 days you must remove the rechargeable battery. Store in a cool environment. |
| 4 | every measurement | data analysis | compare measured data between the measurement locations. Look for any patterns and events that deviate from what is normal or expected. Compare to acceptance intervals. Plot heat flux and temperature data against the other measurements if available. Inspect cable quality, inspect mounting |
| 5 | every month | recharging | the battery needs periodic recharging. We recommend recharging the battery every month. |
| 6 | 12 months | inspection | side by side comparison of two heat flux sensors and their respective thermocouples when mounted side by side. |
| 7 | 2 years | recalibration | recalibration of heat flux sensor and MCU by the sensor manufacturer |
| 8 | | lifetime assessment | judge if the instrument will be reliable for another 2 years, or if it should be replaced |
| 9 | 4 years | | replace the battery of the CR1000, encased in the MCU |
| 10 | 4 years | | replace the rechargeable battery |

9.3 Trouble shooting

Table 9.3.1 *Trouble shooting for ALUSYS*

| | |
|---|--|
| General | <p>Inspect the sensors and MCU for any damage. Inspect the quality of mounting. Check the condition of the cables.</p> <p>Check the datalogger program in particular if the correct sensor properties have been entered.</p> <p>Check the voltages of the rechargeable battery and of the internal system battery on the numeric screen.</p> <p>If problems persist, activate debugMode in the ports & flags panel. Check the debug table below. DebugMode logs the debugTable, which can be submitted to the manufacturer for troubleshooting</p> |
| The HF01 sensor does not give any signal | <p>Use the HF01 manual trouble shooting guide.</p> <p>Check the data acquisition by replacing the sensor with a spare unit.</p> |
| There are doubts about the MCU measurement | <p>Compare measurement results to those with a calibrated multimeter. Short-circuit the input using a 10 Ω resistor. The heat flux signal should be 0 W/m², the temperature signal should reach the panel temperature.</p> <p>A voltage source may be built from a 1.2 VDC battery, and a 1:1000 voltage divider, creating a 1 x 10⁻³ V source. Calculate the expected heat flux and temperature.</p> |
| The sensor signals are unrealistically high or low | <p>Check the cable condition looking for cable breaks.</p> <p>Check the data acquisition by applying a 1 x 10⁻⁶ VDC source to it in the 1 x 10⁻⁶ V range. Look at the measurement result. Check if it is as expected.</p> <p>Check the data acquisition by short circuiting the data acquisition input with a 10 Ω resistor. Look at the output.</p> |
| The sensor signals show unexpected variations | <p>Check the presence of strong sources of electromagnetic radiation (radar, radio).</p> <p>Check the condition and connection of the shield.</p> <p>Check the condition of the sensor cable.</p> <p>Check if the cable is not moving during the measurement.</p> |
| The green measurement LED is blinking slowly (every 3s) | <p>The voltage supplied by the internal battery has dropped below 10 V</p> |
| The green measurement LED is blinking is rapidly | <p>The library file is missing or has been corrupted. Consult chapter 6.3.2. DebugList(1) or DebugList(2) will probably be set to "True"</p> |

If any of the following values are set to “True”, the information on the right is applicable:

Table 9.3.2 *DebugTable for ALUSYS*

| | |
|---------------|---|
| DebugList(1) | NumberOfSensors was set to > 3 while AM25T is set to not connected. Upload the original files as stated in chapter 6.3.2 |
| DebugList(2) | NumberOfSensors was set to < 1 or > MaxSensors(12). Upload the original files as stated in Chapter 6.3.2 |
| DebugList(3) | Scanrate has been set < 0. The software corrected this to 1 (scanrate = 1 min) |
| DebugList(4) | Battery voltage below 10 Volts |
| DebugList(5) | Interval has been set < 4. This is too low for the system (scanrate is 3s). The software corrected this to 30 (interval = 30 sec) |
| DebugList(6) | Unused |
| DebugList(7) | Unused |
| DebugList(8) | Unused |
| DebugList(9) | Unused |
| DebugList(10) | Unused |

Table 9.3.3 *Trouble shooting for Keyboard display*

| | |
|---------------------------------------|---|
| General | Check the Keyboard Display (CR1000KD) manual (CR1000 manual) for trouble shooting |
| The screen seems to be off | Check that the Keyboard Display is properly connected to the MCU Press and hold the 6 key to increase the contrast |
| The screen displays a black rectangle | Press and hold the 4 key to decrease the contrast |
| The contrast is off | Press and hold the 4 key to decrease the contrast or the 6 key to increase the contrast |

9.4 Calibration and checks in the field

We recommend to re-calibrate the MCU and HF01 every 2 years at the manufacturer.

At Hukseflux HF01 sensors are calibrated under the following calibration reference conditions: heat flux of the order of 1500 W/m^2 , low convection, on a surface with zero in-plane conduction, at $90 \text{ }^\circ\text{C}$.

These conditions may not be representative of the your actual measurement condition.

ALUSYS and the sensor model HF01 are most suitable for relative measurements, i.e. monitoring of trends relative to a certain reference point in time or comparing heat flux at one location to the heat flux at another location. Also when performing relative measurements, we recommend you to perform an on-site comparison to verify sensor performance. A comparison is made by mounting multiple sensors side by side, and comparing under conditions – temperature, mounting surface and local convection – representative of your test environment. One sensor must serve as a comparison reference.

Typically this comparison reference sensor is not used for field measurements but stored in a safe place, so that the same comparison may be repeated at a later moment.

If you want to perform accurate absolute measurements, as opposed to relative measurements we recommend that you calibrate sensors under "simulated service conditions". This is done by creating an environment which closely resembles the measurement conditions; the calibration source might even be the object under test itself. Calibrations are typically traceable to electrical power (voltage and resistance) and length (surface area of the calibration source). We recommend to calibrate at different temperatures.

Under all conditions you must make your own uncertainty evaluation and correction for systematic errors.

9.5 Storage of ALUSYS

MCU01 and sensors should be stored in a dry and cool place.

In case the system is stored for a longer time than 60 days, we recommend the rechargeable battery is separately stored or disposed. Consult the battery manufacturer for statements on battery lifetime.

10 Appendices

10.1 Variable names and description

Table 10.1.1 *Explanation of variables and parameters used in the ALUSYS program*

| PARAMETERS USED IN ALUSYS PROGRAM | | |
|--|--|--|
| PARAMETER | DESCRIPTION | UNITS |
| PTemp | Panel temperature | °C |
| Timestamp | Date and time | YYYY-MM-DD HH:MM:SS |
| Record | Number of the record | - |
| Flux (#) | Heat flux of sensor # | $\times 10^3$ W/m ² |
| Ts (#) | Temperature of sensor # | °C |
| E (#) | Sensitivity of sensor # (default 600) | $\times 10^{-9}$ V/(W/m ²) |
| TD (#) | Temperature dependence of sensor # (default 0.000015) | 1/K |
| Tref (#) | Calibration reference temperature of sensor # (default 90) | °C |
| SN | Sensor serial number | ##### |
| Interval | time interval for averaging measurements (default 30) | s |
| scanrate | Data storage time interval for all sensor measurements (default 1) | min |
| Batt volt | Voltage of the rechargeable battery | V |
| Ptemp | Internal MCU temperature | °C |

10.2 Battery removal

The ALUSYS contains two batteries. A rechargeable battery to power the system and an internal system battery to power the system clock and SRAM. The minimum voltages of both batteries are stored in the datafiles, and can be viewed in the numeric display.

The rechargeable battery needs periodic recharging. We recommend recharging the battery every month. It must be removed and stored separately if the equipment is stored for > 60 days. The removal of the rechargeable battery is self explanatory; open the, MCU disconnect the battery clamps and open the battery container.

For removal of the internal system battery: consult the manufacturer.

10.3 EU declaration of conformity



We, Hukseflux Thermal Sensors B.V.
Delftechpark 31
2628 XJ Delft
The Netherlands

in accordance with the requirements of the following directive:

2014/30/EU The Electromagnetic Compatibility Directive

hereby declare under our sole responsibility that:

Product model: ALUSYS
Product type: Measuring system for heat flux and temperature survey

has been designed to comply and is in conformity with the relevant sections and applicable requirements of the following standards:

Emission: EN 61326-1 (2006)
Immunity: EN 61326-1 (2006)
Emission: EN 61000-3-2 (2006)
Emission: EN 61000-3-3 (1995) + A1 (2001) + A2 (2005)
Report: 08C01340RPT01, 06 January 2009

A handwritten signature in blue ink, appearing to be 'Eric Hoeksema', written over a light blue grid background.

Eric HOEKSEMA
Director
Delft
September 08, 2015

